

ACURA B2212: GAUGE CONTROL MODULE LOST F-CAN COMMUNICATION LINE ERROR WITH ACURALINK CONTROL UNIT (XM RECEIVER)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2212 Code Mean?

This code indicates poor communication between the Gauge Control Module and AcuraLink control unit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN system diagnosis test mode A.

What Are The Potential Causes Of The Acura B2212 Code?

Below are some potential causes of this DTC:

- Check for DTCs with the HDS and DTC log data in the navigation system diagnostic mode.
- Poor connections or loose terminals at the AcuraLink control unit (XM receiver)
- "Open" circuit between the AcuraLink control unit (XM receiver) and the gauge control module
- AcuraLink control unit needs to be updated with the latest software
- Faulty acuraLink control unit

Reference Sources

[Acura B2212](#), DTCDECODE.