

ACURA P1300: RANDOM MISFIRE DETECTED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Does The Acura P1300 Code Mean?

Engine running under positive torque conditions, and the PCM detected a misfire in 2 or more cylinders.

What Are The Potential Causes Of The Acura P1300 Code?

- CKP or CMP sensor signal erratic or intermittent
- Fuel system problem affecting more than one cylinder
- Ignition system problem affecting more than one cylinder
- Base engine mechanical fault affecting more than one cylinder

Reference Sources

[Acura P1300](#), DTCDECODE.