CIRCUIT FAULT (BANK 1)			
		OVERVIEW	
Coveritor			lich
Severity	:		High
DIY Difficulty Level	:	Advar	nced
Repair Cost	:	\$300-\$500	

What Does The Acura P1317 Code Mean?

Engine started, and the PCM detected an unexpected condition on the Spark Plug Detection Module circuit for Cylinder Bank 1.

What Are The Potential Causes Of The Acura P1317 Code?

- Spark Plug Detection Module circuit open or shorted to ground
- Spark Plug Detection Module circuit is shorted to system power
- Spark Plug Detection Module is damaged or has failed
- PCM has failed

Reference Sources

Acura P1317, DTCDECODE.

