

ACURA P1367: TOP DEAD CENTER SENSOR 2 NO SIGNAL

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$250
Can I Still Drive?	:	No

What Does The Acura P1367 Code Mean?

Engine cranking or running; and the PCM did not detect any signals from the Top Dead Center 2 (TDC2) sensor during the CCM test.

Note: The engine will start and run without the TDC sensor 2 signal.

What Are The Potential Causes Of The Acura P1367 Code?

- TDC2 signal circuit is open or shorted to ground
- TDC2 pickup assembly or its pulse rotor is damaged
- TDC2 is damaged or has failed
- PCM has failed

Reference Sources

[Acura P1367](#), DTCDECODE.