ACURA P1549: CHARGING SYSTEM HIGH VOLTAGE		
	O,	/ERVIEW
Severity	:	н
DIY Difficulty Level	:	Advand
Repair Cost	:	\$375-\$1100
Can I Still Drive?	: '	⁄es

What Does The Acura P1549 Code Mean?

The IGP terminal voltage is 16.0 volts or more for at least 60 seconds. The execution time is continuous.

NOTE: If a high voltage battery (24 V, etc.) is connected to the vehicle, this DTC can be stored.

What Are The Potential Causes Of The Acura P1549 Code?

- Poor connections or loose terminals at the alternator and the main under-hood fuse box
- Faulty alternator

Reference Sources

Acura P1549, DTCDECODE.