

ACURA P1788: A/T ATSDLA SIGNAL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura P1788 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the A/T ATSDLA signal circuit to the TCM.

Note: The D4 lamp on the dash will flash 19 times if this code is set.

What Are The Potential Causes Of The Acura P1788 Code?

- A/T ATSDLA signal circuit to the TCM is open
- A/T ATSDLA signal circuit to the TCM is shorted to ground
- A/T ATSDLA signal circuit to the TCM is shorted to VREF
- TCM or PCM has failed

Reference Sources

[Acura P1788](#), DTCDECODE.