AUDI P1295: TURBOCHARGER BYPASS VALVE THROUGHPUT FAULTY			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$300-\$400	
Can I Still Drive?	:	Yes	

## What Does The Audi P1295 Code Mean?

Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, coolant temperature at least 80-degrees Celicius.

## What Are The Potential Causes Of The Audi P1295 Code?

- Charge air system check for leaks
- Recirculating valve for turbocharger is faulty
- Turbocharging system may be damaged
- Vacuum diagramfor turbocharger needs adjusting
- Wastegate bypass regulator valve is faulty
- Bypass solenoid power supply

## **Reference Sources**

Audi P1295, DTCDECODE.

