

AUDI P1295: TURBOCHARGER BYPASS VALVE THROUGHPUT FAULTY

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$400
Can I Still Drive?	:	Yes

What Does The Audi P1295 Code Mean?

Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, coolant temperature at least 80-degrees Celcius.

What Are The Potential Causes Of The Audi P1295 Code?

- Charge air system check for leaks
- Recirculating valve for turbocharger is faulty
- Turbocharging system may be damaged
- Vacuum diagram for turbocharger needs adjusting
- Wastegate bypass regulator valve is faulty
- Bypass solenoid power supply

Reference Sources

[Audi P1295](#), DTCDECODE.