

What Does The Audi P1359 Code Mean?

This code is set in this condition:

Key on or Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, and the ECM detected the voltage of the ignition was outside the designed parameters.

What Are The Potential Causes Of The Audi P1359 Code?

Below are some potential causes of this DTC:

- Fuel pump relay faulty
- Camshaft position sensor has failed
- Engine speed sensor has failed
- Circuit wires have shorted to ground or are open
- Ignition coils with power output stages are faulty
- ECM has failed

Reference Sources

Audi P1359, DTCDECODE.

