

AUDI P13D4: SENSOR FOR INTERNAL PRESSURE OF CYLINDER 3 ELECTRICAL MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	No

What Are The Potential Causes Of The Audi P13D4 Code?

- Faulty Glow Plug in Cylinder 3
- Glow Plug in Cylinder 3 harness is open or shorted
- Glow Plug in Cylinder 3 circuit poor electrical connection

Reference Sources

[Technical Service Bulletin for P13D4](#) - Audi of America, Inc; 2010–2014 A3 TDI & 2015 A3 Sportback TDI