

AUDI P1470: EVAP EMISSION CONTROL LDP CIRCUIT ELECTRICAL MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$350-\$550
Can I Still Drive?	:	Yes

What Does The Audi P1470 Code Mean?

Key on, KOEO Self-Test enabled, and the ECM detected an unexpected voltage condition on the EVAP emission control leak detection pump circuit.

What Are The Potential Causes Of The Audi P1470 Code?

- EVAP canister system has an improper or broken seal
- Evaporative Emission (EVAP) canister purge regulator valve 1 is faulty
- Leak Detection Pump (LDP) is faulty
- ECM has failed

Reference Sources

[Audi P1470](#), DTCDECODE.