

What Does The Audi P1613 Code Mean?

Engine started, VSS over 1 mph, and the ECM detected a problem in the Transmission Control system during the self-test.

What Are The Potential Causes Of The Audi P1613 Code?

- Open/short circuit to ground from the MIL to the ECM.
- The ECM has failed
- The MIL light has failed (check bulb)

Reference Sources

Audi P1613, DTCDECODE.