

## AUDI P1624: MIL REQUESTED SIGNATURE ACTIVE

### OVERVIEW

Severity	:	<div></div> High
DIY Difficulty Level	:	<div></div> Advanced
Repair Cost	:	\$800-\$1500
Can I Still Drive?	:	No

### What Does The Audi P1624 Code Mean?

This code indicates the condition that ignition is on, the ECM detected a control module malfunction. To achieve optimal anti-theft protection for the vehicle, an anti-theft immobilizer is installed. The anti-theft immobilizer is a system for enabling and locking the Engine Control Module (ECM).

### What Are The Potential Causes Of The Audi P1624 Code?

Below are some potential causes of this DTC:

- (If ECM was replaced) ECM ID not the same as the replaced unit
- ECM has failed
- Voltage supply for Engine Control Module (ECM) has shorted

### Reference Sources

[Audi A4 Avant 95-01 Service Repair Manual](#), page 60.