

AUDI P1702: MALFUNCTION CANNOT ACTIVATE CONTROL MODULE REPLACEMENT FUNCTION, SINCE ANOTHER MALFUNCTION WITH EQUAL PRIORITY IS PRESENT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$500-\$900
Can I Still Drive?	:	No

What Does The Audi P1702 Code Mean?

Calculation of current data stored in TCM is not correct comparing with pre-stored checking data in TCM.

What Are The Potential Causes Of The Audi P1702 Code?

- Clear the trouble code, and recheck for the same code.
- If this trouble code resets, the control module must be replaced.

Reference Sources

- Audi, 2014, [A8/A8L/S8 Quick Reference Specification Book](#), page 321.
- Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 154.