

AUDI P17B9: CLUTCH POSITION SENSOR

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Audi P17B9 Code Mean?

Engine start, completed

Reference Sources

Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 182.