

AUDI P17BD: SHIFT POSITION SENSOR

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Audi P17BD Code Mean?

Malfunction Criteria and Threshold Value:

Short to Battery (+), sensor output Voltage high, > 4.5 V

Reference Sources

Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 181.