

AUDI P1854: DATA-BUS DRIVING GEAR HARDWARE FAULTY

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Audi P1854 Code Mean?

This code indicates initialize failure and/or no acknowledge 2 attempts of initialize, 500 ms after ign. ON.

What Are The Potential Causes Of The Audi P1854 Code?

Below are some potential causes of this DTC:

- Check the Terminal resistance for CAN-bus
- Data-Bus wires have short
- Data-Bus components are malfunctioning
- ECM has failed

Reference Sources

[Audi P1854](#), DTCDECODE.