

AUDI P3025: ANGLE SENSOR 1 (ON THROTTLE DRIVE 2 POWER ACCELERATOR ACTUATION)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Audi P3025 Code Mean?

TPS electrical range no failure unthrottled condition not fulfilled engine speed > 480 RPM OR engine speed > 1200 RPM TPS electrical range no failure unthrottled condition not fulfilled engine speed > 480 RPM

Reference Sources

- Audi, 2013, [A8/A8L/S8 Quick Reference Specification Book](#), page 300.
- Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 142.