LEVEL TOO LOW		
		OVERVIEW
Severity	:	High
Severity	•	Tilgi
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$121-\$160

What Does The BMW P1129 Code Mean?

Engine started, and the oil sensor has detected that the level is too low.

What Are The Potential Causes Of The BMW P1129 Code?

Top off the oil

Reference Sources

BMW P1129, DTCDECODE.