BMW P1663: EWS (ELECTRONIC IMMOBILIZER) ROLLING CODE FAULTY STORAGE IN EEPROM OVERVIEW Severity: Medium DIY Difficulty Level: Intermediate Repair Cost: \$75-\$200 Can I Still Drive?: Yes

What Does The BMW P1663 Code Mean?

Key on the DME detected an electrical malfunction regarding the EWS. Check the EWS fuse, the ECU or CAN for fault, turn the ignition off and then on to repeat start calibration.

What Are The Potential Causes Of The BMW P1663 Code?

- Circuit from the MIL to the DME
- ECU Failure, BUS system failure
- Circuit from the EPC to the DME
- Defective CAS

Reference Sources

BMW P1663, DTCDECODE.

