

## BMW P1782: BRAKE PEDAL SIGNAL PLAUSIBILITY

### OVERVIEW

<b>Severity</b>	:		High
<b>DIY Difficulty Level</b>	:		Intermediate
<b>Repair Cost</b>	:	\$100-\$200	
<b>Can I Still Drive?</b>	:	No	

### What Does The BMW P1782 Code Mean?

The CAN Message signal error flag alive counter or check sum is sending/receiving an incorrect signal. There is no alteration of the alive counter and no wrong check sum. The DME-CAN Connection is okay. The CAN-Bus is okay and the ignition is on.

### What Are The Potential Causes Of The BMW P1782 Code?

Below are some potential causes of this DTC:

- Mechanical malfunction in the brake system
- Brake solenoid circuits are open or grounded
- DME/TCM has failed

### Reference Sources

[BMW P1782](#), DTCDECODE.