

CADILLAC B1513: INSTRUMENT PANEL CLUSTER VOLTAGE LOW INPUT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$600-\$900
Can I Still Drive?	:	No

What Does The Cadillac B1513 Code Mean?

DTC P1327 not set, engine started, engine speed over 1,500 rpm, and the PCM received a "low voltage" message on the Class 2 data line from the Instrument panel cluster (IPC). The IPC detected the system voltage was less than 10.5v for 30 seconds

What Are The Potential Causes Of The Cadillac B1513 Code?

- Check the operation of the Charging system (Generator)
- The charge indicator and driver warning message are set in the driver information center (DIC)
- IPC is damaged or has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).