

CADILLAC C1276: DELIVERED TORQUE SIGNAL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Cadillac C1276 Code?

Below are some potential causes of this DTC:

- An open in the delivered torque circuit.
- An short to ground or voltage in the delivered torque circuit.
- A wiring problem, terminal corrosion, or poor connection in the delivered torque circuit.

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).