

## CADILLAC C12F7: ABS BOOST PRESSURE SENSOR AND REGENERATIVE AXLE PRESSURE SENSOR NOT PLAUSIBLE

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$200
Can I Still Drive?	:	Yes

### What Does The Cadillac C12F7 Code Mean?

Ignition ON. Ignition voltage is greater than 10 volts.

### What Are The Potential Causes Of The Cadillac C12F7 Code?

Internal sensor failure is detected.

### Reference Sources

[Cadillac C12F7](#), DTCDECODE.