CADILLAC P1286: TP SENSORS MISMATCH		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1286 Code Mean?

Conditions for setting the DTC:

DTCs <u>P0606</u>, <u>P1517</u>, or <u>P1518</u> are not set. The ignition switch is in the crank or run position. The ignition voltage is greater than 5.23 volts.

How Can You Fix The Cadillac P1286 Code?

Inspect the TAC module connectors for signs of water intrusion. If water intrusion occurs, multiple DTCs may set without any circuit or component conditions found during diagnostic testing.

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

