

CADILLAC P1514: THROTTLE BODY PERFORMANCE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$620
Can I Still Drive?	:	No

What Does The Cadillac P1514 Code Mean?

DTC [P0601](#), [P0602](#), [P0606](#), [P1515](#), [P1516](#), [P1517](#) and [P1518](#) not set, [P1120](#), [P1220](#) and [P1221](#) not active at the time this code set, or P1120 and P1220 not set at the same time, engine speed over 500 rpm.

What Are The Potential Causes Of The Cadillac P1514 Code?

- Inspect the throttle blade for damage and/or proper installation
- Inspect the TAC module connectors for signs of water intrusion. When water intrusion occurs, multiple codes can set with no circuit or component faults apparent during diagnostic testing.

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).