

CADILLAC P1545: AIR CONDITIONING CLUTCH RELAY CONTROL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P1545 Code?

- A/C compressor clutch coil is damaged (it may be shorted)
- A/C clutch relay is damaged or has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).