

CADILLAC P1553: ADAPTIVE CRUISE CONTROL SIGNAL CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P1553 Code?

An FLS radar out of alignment condition may be as a result of tampering with the DSCC module mounting structures/brackets or the adjuster settings. An out of alignment condition may also be a result of damage to the front section vehicle or the DSCC module.

Reference Sources

GM, 2014, [2014 Cadillac ELR \(EREV\) History DTCs Leading To Misdiagnosis or Needless Component Replacement](#).