

CADILLAC P1572: TCS ACTIVE CIRCUIT LOW VOLTAGE TOO LONG

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$320-\$1000
Can I Still Drive?	:	Yes

What Does The Cadillac P1572 Code Mean?

Conditions for Setting the DTC. No TFP Val Position Sw DTC P1810 The transmission is in Park or Neutral. The traction control is active. All conditions are satisfied for 6.4 seconds.

What Are The Potential Causes Of The Cadillac P1572 Code?

Inspect the wiring for any poor electrical connections at the PCM. Inspect the wiring at the TCC brake switch. Look for the following conditions:

- A bent terminal
- A backed out terminal
- A damaged terminal
- Poor terminal tension

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).