CADILLAC P1574: STOPLAMP SWITCH CIRCUIT MALFUNCTION OVERVIEW Severity: Medium DIY Difficulty Level: Intermediate Repair Cost: \$30-\$100

What Does The Cadillac P1574 Code Mean?

DTC <u>P0703</u>, <u>P1575</u> and <u>P1602</u> not set, engine started, ABS and Traction Control inactive or failed, VSS over 20 mph, then remained over 3 mph during the test, difference in speed between the non-driven wheels and driven wheels less than 6 mph.

Yes

Reference Sources

Can I Still Drive?

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

