

CADILLAC P1600: TCM INTERNAL WATCHDOG OPERATION (4L60-E)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes

What Does The Cadillac P1600 Code Mean?

Key on or engine running; TCM High side driver open, and the PCM received a signal that indicated the TCM detected an unexpected voltage condition on the internal TCM Power Control relay.

What Are The Potential Causes Of The Cadillac P1600 Code?

- Power control relay circuit is open, shorted to ground or to B+
- Power control relay is damaged or has failed
- TCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).