

CADILLAC P1604: LOSS OF IPC SERIAL DATA

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$175-\$250
Can I Still Drive?	:	Yes

What Does The Cadillac P1604 Code Mean?

Engine started with the engine speed more than 500 rpm for 10 seconds, and the PCM did not detect any Instrument Panel Cluster (IPC) serial data or it detected invalid serial data from the IPC for 11 seconds during the CCM test.

How Can You Fix The Cadillac P1604 Code?

- Check the serial data circuit for a poor connection at the IPC
- Perform the IPC System Check
- Perform the Powertrain Onboard Diagnostic System Check

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).