

## CADILLAC P1610: LOSS OF PLATFORM ZONE MODULE SERIAL DATA

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$175-\$250
Can I Still Drive?	:	Yes

### What Does The Cadillac P1610 Code Mean?

Key on for 5 seconds and the PCM did not detect serial data from the Platform Zone Module (PZM) or it was unable to communicate with the PZM for 11 seconds.

### What Are The Potential Causes Of The Cadillac P1610 Code?

- Check the serial data circuit for a poor connection at the PZM
- Perform the PZM System Check
- Perform the Powertrain Onboard Diagnostic System Check

### Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).