

CADILLAC P1625: TCM SYSTEM RESET (4L30-E)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes

What Does The Cadillac P1625 Code Mean?

Engine started; and the TCM detected an unexpected voltage condition on the TCM Power Control relay circuit (the relay is internal to the ECM) during the CCM test.

What Are The Potential Causes Of The Cadillac P1625 Code?

- TCM power control relay control circuit is open or shorted to B+
- TCM power control relay has failed, or the TCM has failed

Reference Sources

GM, 2013, [Service Bulletin - Prior To Any Circuit Testing](#).