CADILLAC P179B: RANGE STATE COMMAND CIRCUIT			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:	Ad	lvanced
Repair Cost	:	\$500-\$900	
Can I Still Drive?	:	Yes	

What Does The Cadillac P179B Code Mean?

The engine is running. Ignition voltage is 8-18 V.

What Are The Potential Causes Of The Cadillac P179B Code?

The control solenoid valve assembly has detected a Range State Command rolling count error for 0.2 seconds.

Reference Sources

Cadillac P179B, DTCDECODE.

