

CADILLAC P179B: RANGE STATE COMMAND CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$500-\$900
Can I Still Drive?	:	Yes

What Does The Cadillac P179B Code Mean?

The engine is running. Ignition voltage is 8-18 V.

What Are The Potential Causes Of The Cadillac P179B Code?

The control solenoid valve assembly has detected a Range State Command rolling count error for 0.2 seconds.

Reference Sources

[Cadillac P179B](#), DTCDECODE.