

CADILLAC P181C: INTERNAL MODE SWITCH 2 R1 CIRCUIT LOW VOLTAGE

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	Yes

What Does The Cadillac P181C Code Mean?

The ignition is ON. Ignition voltage is greater than 6.0 V.

What Are The Potential Causes Of The Cadillac P181C Code?

The internal mode switch state does not match the selected gear for 3 seconds.

Reference Sources

[Cadillac P181C](#), DTCDECODE.