

## CADILLAC P1A52: DRIVE MOTOR 2 CONTROL MODULE NOT PROGRAMMED

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$500-\$3500
Can I Still Drive?	:	No

### What Does The Cadillac P1A52 Code Mean?

The control module has detected an internal malfunction.

### Reference Sources

[Cadillac P1A52](#), DTCDECODE.