

CADILLAC U1000: CLASS 2 COMMUNICATION MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

What Does The Cadillac U1000 Code Mean?

Modules connected to the Class 2 circuit monitor for serial data communications during normal vehicle operation. Operating information and commands are exchanged among the modules.

What Are The Potential Causes Of The Cadillac U1000 Code?

- Class 2 circuit is open, shorted to ground or shorted to power
- PCM ignition power circuit(s) has a high resistance condition
- PCM main ground circuit(s) has a high resistance condition
- SDM (module) could be shorted pulling the voltage low

Reference Sources

- GM, 2002, [Service Bulletin](#).
- GM, 2016, [Service Bulletin](#) - No Crank Key Stuck In Ignition Lock Cylinder Multiple ECM Codes And U1000 Set In Class 2 Modules.