

CADILLAC U1026: LOSS OF ATC CLASS 2 COMMUNICATION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1026 Code Mean?

Key on or engine running; and a module detected that it could not communicate with the ATC controller for 1 second. Modules connected to the Class 2 circuit monitor for data communications during normal vehicle operation.

What Are The Potential Causes Of The Cadillac U1026 Code?

- Check for a loose connection at the ATC module
- Test the main power and ground circuits to the ATC module
- Check the Class 2 serial data circuit to the ATC module
- ATC module may have failed

Reference Sources

[Cadillac U1026](#), DTCDECODE.