

CADILLAC U1153: LOSS OF COMMUNICATIONS WITH HVAC

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac U1153 Code Mean?

Conditions for setting the DTC:

The module does not receive a state of health (SOH) message back from the CCP. The module retries the request 3 times. The module then sets DTC U1153. This DTC only sets if [U1300](#) or [U1301](#) are not current.

Note:

- DTC U1153 does not normally represent a failure within the module.
- When loss of class 2 serial data communication DTCs (DTCs with a letter U prefix) are stored as history, know all of the possible serial data DTCs set in each module before diagnosis

Reference Sources

GM, 2016 [Service Bulletin](#) - No Crank Key Stuck In Ignition Lock Cylinder Multiple ECM Codes And U1000 Set In Class 2 Modules.