

CADILLAC U1162: LOSS OF REAR DRIVER DOOR MODULE SBI

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac U1162 Code Mean?

The DDM does not receive an SOH message back from the LRDM. The DTC only sets if [U1300](#) or [U1301](#) are not current.

Note:

- DTC module U1162 does not normally represent a failure within the module.
- If the DTC is a history DTC, the problem may be intermittent.

Reference Sources

[Cadillac U1162](#), DTCDECODE.