CADILLAC U1170: LOSS OF DRIVER DOOR SWITCH SB		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1170 Code Mean?

The DDM does not receive an SOH message back from the LH front power window switch. The DTC only sets if <u>U1300</u> or <u>U1301</u> are not current.

What Are The Potential Causes Of The Cadillac U1170 Code?

- DTC module U1170 does not normally represent a failure within the module.
- If the DTC is a history DTC, the problem may be intermittent.

Reference Sources

Cadillac U1170, DTCDECODE.