

CADILLAC U1884: HYBRID CONTROL MODULE (HCM) LOST COMMUNICATION WITH PASSENGER DOOR MODULE (PDM)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1884 Code Mean?

Voltage supplied to the module is in the normal operating voltage range of 9-16 volts.

What Are The Potential Causes Of The Cadillac U1884 Code?

For DTC U1892, ensure all power and ground circuits to the electric-hydraulic power steering (EHPS) module including the motor are tested. A loss of voltage or ground to the EHPS hydraulic motor as well as to the module may cause a loss of power.

Reference Sources

[Cadillac U1884](#), DTCDECODE.