

CHEVROLET C120C: BRAKE PEDAL POSITION SENSOR 4 NOT PLAUSIBLE

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	No

What Does The Chevrolet C120C Code Mean?

This EBCM detects the master cylinder pressure is high when brake master cylinder piston position sensor is reading low travel.

Reference Sources

[Chevrolet C120C](#), DTCDECODE.