# CHEVROLET C12B6: HIGH PRESSURE ACCUMULATOR PRESSURE SENSOR SHORT TO GROUND OR OPEN

#### **OVERVIEW**

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$50-\$300

**Can I Still Drive?** : Yes (Short-term only)

# What Does The Chevrolet C12B6 Code Mean?

This code means that the HPA (High Pressure Accumulator) pressure sensor is either open or shorted to ground.

## What Are The Potential Causes Of The Chevrolet C12B6 Code?

Below are some potential causes of this DTC:

- A short to battery is detected on the sensor signal circuit.
- A short to ground or open is detected on signal circuit.
- Signal is erratic and changes faster than physically allowed.

## **Reference Sources**

<u>Chevrolet Volt Hybrid DTC</u> - OBDG01 HYBRID Diagnostics Document, page 563.

