

CHEVROLET C12BB: ABS REGENERATIVE AXLE PRESSURE SENSOR ERRATIC

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$800
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet C12BB Code Mean?

Ignition ON. Ignition voltage is greater than 10 volts.

Signal is erratic and changes faster than physically allowed.

Reference Sources

[Chevrolet C12BB](#), DTCDECODE.