## CHEVROLET C12BC: BRAKE BOOST REGULATION PRESSURE SENSOR SHORT TO GROUND OR OPEN OVERVIEW Severity: High DIY Difficulty Level: Intermediate Repair Cost: \$250-\$800 Can I Still Drive?: Yes (Short-term only)

## What Does The Chevrolet C12BC Code Mean?

This code indicates that the boost pressure sensor is either open or shorted to ground.

## What Are The Potential Causes Of The Chevrolet C12BC Code?

Below are some potential causes of this DTC:

- Internal sensor failure is detected.
- A short to battery is detected on the sensor signal circuit.
- A short to ground or open is detected signal circuit.
- The boost pressure being commanded is not being achieved.
- Signal is erratic and changes faster than physically allowed.

## **Reference Sources**

Chevrolet Volt Hybrid DTC - OBDG01 HYBRID Diagnostics Document, page 564.

