

CHEVROLET P1020: CAMSHAFT PHASING SYSTEM MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1020 Code Mean?

Engine operating on CNG, PCM not in Fuel Shutoff or Decel Fuel Shutoff modes, system voltage from 6-18v, and the FICM (module) detected an invalid fuel injector PWM signal.

What Are The Potential Causes Of The Chevrolet P1020 Code?

- AF fuel mode relay circuit (odd bank, even bank) is open
- AF enable circuit is open or shorted to ground
- FICM is damaged or it has failed

Reference Sources

[Chevrolet P1020](#), DTCDECODE.