

## CHEVROLET P10CC: EXHAUST AFTERTREATMENT FUEL INJECTOR CONTROL CIRCUIT SHORTED

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chevrolet P10CC Code Mean?

This code indicates that the ECM detects a short in the indirect fuel injector control circuit.

Conditions for setting the DTC: Battery Voltage is greater than 11 V. Engine speed is greater than 600 RPM.

### Reference Sources

[Chevrolet P10CC](#), DTCDECODE.